

7 Dec.1964



Technical Information

IMPORTANT MODIFICATIONS RECENTLY INTRODUCED

Joint
washer

<u>From Engine No.</u>	<u>10AMW-TA-H 318950)</u>	<u>AUSTIN 1100</u>
	<u>10AMW-TA-L 317011)</u>	<u>MORRIS 1100</u>
	<u>10GR-TA-H 60780)</u>	
	<u>10GR-TA-L 57465)</u>	<u>MG 1100</u>
	<u>10GRB-TA-H 3760)</u>	
	<u>10V-TA-H 1711)</u>	<u>VANDEN PLAS</u>
	<u>10V-TA-L 905)</u>	<u>PRINCESS 1100</u>

Improved design

Introduction of new joint washer for engine front mounting plate to crankcase.

<u>Old Part No.</u>	<u>Description</u>	<u>Qty.</u>	<u>New Part No.</u>
12G 213	Washer - joint - engine front mounting plate	1	12G 619

Interchangeable.

Power
unit

<u>From Engine No.</u>	<u>18GB-U-H 101)</u>	
	<u>18GB-RU-H 501)</u>	<u>MGB</u>
	<u>18GB-U-L 1501)</u>	
	<u>18GB-RU-L 1521)</u>	

Introduction of new power unit with 5 main bearings. For full description of parts changes, refer to Parts List Amendments PMG/775 to 779 inclusive.
NB. Always quote in full engine prefix and serial number in all orders, Warranty Claims, correspondence etc.

Not interchangeable.